

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 75.15**SOURCE INSPECTION REPORT****Resident Engineer:**Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** SIR-001148**Date Inspected:** 09-Nov-2009**Project Name:** SAS Superstructure**OSM Arrival Time:** 730**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1500**Contractor:** Shanghai Pujiang Cable Co. (SPCC)**Location:** Bao Steel, Shanghai**Quality Control Contact:** Mr. Pei**Quality Control Present:** Yes No**Material transfer:** Yes No N/A**Sampled Items:** Yes No N/A**Stock Transfer:** Yes No N/A**OK to Cut:** Yes No N/A**Rebar Test Witness:** Yes No N/A**Delayed/Cancelled:** Yes No N/A**Other:** witnessed tensile tests for galvanized wire**Bridge No:** 34-0006**Component:** 5.4mm diameter galvanized wire**Bid Item:** 66A**Lot No:** B240**Summary of Items Observed:**

Caltrans QA Inspector Mr. Wai Pau traveled to Bao Steel to witness tensile tests for galvanized wire from coil # h30911-251-1/2 thru h30911-280-1/2. The coil heat number is 558343. All the tensile tests have been recorded on an electronic spreadsheet and accepted by Bao Steel technician. Caltrans QAI verified that accuracy of tensile strength test readings that were indicated on digital indicator at the time of rupture for each wire. Based on Caltrans QA observation, the tensile tests appeared to be in compliance with requirements of the Caltrans Special Provision and contract documents. The 6th batch production and tensile tests have been completed.

Summary of Conversations:

As notes within report above.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Serge Sinevod 13482570045 , who represents the Office of Structural Materials for your project.

Inspected By: Pau,Wai

Quality Assurance Inspector

Reviewed By: Clifford,William

QA Reviewer